

# PowerValue 11 RT G2 1-3kVA

## Revision history

Revision number	Chapter	Description	Date
REV-A	N/A	First release	27.02.2020
REV-B	3.3	In the PowerValue 11 RT G2 3kVA S rear view picture. Corrected the AC input current from 16A to 20A	08.07.2020
REV-C	1.3	Updated the *ESD” product standard	16.06.2021
	1.3	Updated the “EFT” product standard	
	3.1	In the “Unpacking list”, corrected the number of UPS stands (supports) from 2 to 4.	
	3.1	In the “Unpacking list”, added the “Terminal Block cover (only for 3KS)”	
	3.3.2	Updated the UPS rear panel pictures of all product ranges. (External battery module rear view excluded).	
	4.1.2	Corrected the bypass buzzer status from 10 minutes to 10 seconds.	
	6.3	Updated the “Emergency power off” pictures.	
	7.2	Corrected the “Inverter output short” fault event icon	

---

<b>REV-D</b>	3.2.4.1	Corrected the following sentence, from: “ This procedure is suitable for 19-inch rack cabinet installation with a <b>MINIMUM</b> depth of 800mm.”  To: ““ This procedure is suitable for 19-inch rack cabinet installation with a <b>MAXIMUM</b> depth of 800mm.”	06.07.2022
	4.6	Added the line “NAL: No Alarm” in the output dry contact screen	
	Back cover	Updated company address	

---